

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 12236

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080079-7

RECEIVED FROM

DATE REC'D

P.O. NO.

VENDOR PACKING SLIP NO.

Plant #9

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	REMARKS
2	122	000000	143	0	10					
Drawing No. and Description: Motor Intervalometer IIP 7722										
						QUANTITY				
						ACCEPTED	REJECTED			
						2	1			

RECEIVED
BYINSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 12241

2761 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D

P.O. NO.

VENDOR PACKING SLIP NO.

Plant #9

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	REMARKS
27	122	000000	069	0	12	1				
Drawing No. and Description: Relay IPDY-28V MED-SD-26.5 with sockets IIP 7724 & 7723										
						QUANTITY				
						ACCEPTED	REJECTED			
						27	1			

RECEIVED
BYINSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080079-7